

Execution Error: External Pause/Torch Breakaway Detected

Error:

VMD software displays an error stating Execution Error: External Pause/ Torch Breakaway Detected.

Verification:

- 1. Breakaway (1) status icon is yellow and states Open.
- 2. Remove the torch holder from the breakaway mount on the Z axis column and jump the bottom two bars to verify the breakaway circuit is working. If the Breakaway (1) status remains open contact support to have a case opened.



Solution:

- 1. Reseat the torch holder to the breakaway mount on the Z axis column. See Cause #1.
- 2. Clean the torch breakaway saddles of any rust or debris. See Cause #2.



- 3. Verify the Breakaway cable is fully seated into both the Accumove Breakaway port and the pigtail on the breakaway. See Cause #3.
- 4. Check the Breakaway cable and pigtail for any damaged or missing pins. See Cause #4.

Execution Error: External Pause/Torch Breakaway Detected

DOC #:7214-0-US70-61118-DS-1-1

Rev#:00

Rev Date:06/12/18







Execution Error: External Pause/Torch Breakaway Detected

Verification: (cont'd)

- 5. Adjust the magnet in the center of the breakaway mount so that it is flush with the black plastic base. See Cause #5.
 - a. Unbolt the breakaway mount from the Z-axis column.
 - b. Loosen the 3 set screws on the back of breakaway mount located behind the magnet.



- c. Tighten the countersunk bolt going through the front of the mag net until the magnet is flush with the black plastic base.
- d. Tighten the 3 set screws noted in step B until snug.
- e. Mount the breakaway mount to the Z-axis column.

Cause:

- 1. The connection between the torch holder and the breakaway mount was loose momentarily.
- 2. There was resistance between one or more of the metallic balls and its corresponding saddle keeping the breakaway circuit open.
- 3. There was a loose connection between the breakaway mount and the Accumove controller keeping the breakaway circuit open.
- 4. If one or more pins are damaged or missing then the breakaway cable needs to be replaced. This may have been caused by improper installation of the breakaway cable.
- 5. Improper adjustment of the magnet can cause poor magnet strength or interference with the torch holder plate.

Execution Error: External Pause/Torch Breakaway Detected

DOC #:7214-0-US70-61118-DS-1-1

Rev#:00

Rev Date:06/12/18



