





Step 1:

RCHMATE

A Lincoln Electric Company

Unscrew each of the three screws on the back side of the side cover as shown in Figs. 2a & b with a 1/8 Allen Wrench. Remove the cover (Fig. 2b) carefully as it has the potential of falling as well as possible pinch points.



(a) (b) Fig. 2: Removing the side cover.

Step 2:

Loosen each of the five screws on the side guard with a 1/8 Allen Wrench as shown in Fig. 3a by the arrows, but avoid loosening the screws with the yellow circle. Make sure not to fully remove the screws (Fig 3b).



2 Replacing the 4x00 Y-Axis Motor Belt DOC #: 7301-0-US70-111318-AM-02-02 LINCOLN Cutting



Step 3:

RCHMATE

A Lincoln Electric Company

Slide the side guard in the direction shown in Fig. 4 to move the bottom set of screws over the large diameter holes.



Step 4:

Fig. 4: Slide the side guard in the direction shown.

Once the screw head is over the larger diameter hole on the side guard, again slide in the direction shown in Fig. 5 to remove the side guard. The guard may be heavy and has the possibility to fall, so it is recommend to get assistance during this step.



Pro Tip:

This would be a good time to clear any dirt and debris from the cassette rail and channel.

Fig. 5: Slide side guard in the direction shown to remove it.

3 Replacing the 4x00 Y-Axis Motor Belt DOC #: 7301-0-US70-111318-AM-02-02





Step 1:

Replacing the 4x00 Y-Axis Motor Belt

Part 2:

Removing the side motor shown in Fig. 6a.

Disconnect the motor cable by pressing down on the release switch and pulling apart as shown in Fig. 6a & b.



(a) (b) Fig. 6: Disconnecting the motor cable.

Step 2:

Remove the two shoulder bolts with a 3/16 Allen Wrench from the motor mount as shown in Fig. 7a & b, ensuing to avoid pinch points as well as dropping the motor.



7: Removing the two shoulder bolts from the motor mount.

4 Replacing the 4x00 Y-Axis Motor Belt

DOC #: 7301-0-US70-111318-AM-02-02





Step 3:

Once the motor cable is disconnected and the shoulder bolts are removed, pull the motor up and out in the directions shown in Fig. 8 to remove the motor from the gantry assembly.



Fig. 8: Removing the motor from the gantry assembly.











Step 3: Remove the four screws shown in Fig. 11 with a 9/64 Allen Wrench . Fig. 11: Remove the four screws shown. Remove the four aluminum bushings shown in Fig. 12. Step 4: Fig. 12: Removing aluminum bushings. Replacing the 4x00 Y-Axis Motor Belt 7 LINCOLN Cutting DOC #: 7301-0-US70-111318-AM-02-02 ELECTRIC **Systems**



Step 5:

Push up on the belt from the large pulley to release it from the small pulley. Remove the belt from the motor assembly as shown in Fig. 13.



Fig. 13: Removing the belt.











Step 3:

Place the aluminum bushings as shown and tighten the four screws with a 9/64 Allen Wrench as shown in Fig. 16.



Fig. 16: Reinstalling the aluminum bushings.

Step 4:

Tighten the set screw with a 5/64 Allen Wrench as shown in Fig. 17 in small increments (1/8 to 1/4 of a turn at a time). Squeeze the belt with approximately 1 pound of force to make sure that the belt is not too loose or too tight. When squeezing the belt from both sides, there should be a maximum deflection between 1/16 to 1/8 of an inch. The arrows indicate how the belt should be squeezed to determine proper tension.



Fig. 17: Setting the proper tension on the belt.







Step 5:

Once the proper tension has been achieved, tighten the four screws as shown in Fig. 18 with a 9/64 Allen Wrench to secure the motor into position.



Fig. 18: Tightening the four screws.







Part 5:

Reinstalling the Side Motors

Step 1:

Place and secure the side motor into the slot with the long screw on the left and short screw on the right side as shown in Fig. 19a-c with a 3/16 Allen Wrench.



Step 2:

Reconnect the motor cable as shown in Fig. 20a & b. Make sure the release switch snaps into position so that the two ends are locked into position.



12 Replacing the 4x00 Y-Axis Motor Belt DOC #: 7301-0-US70-111318-AM-02-02





Step 3:

Position the motor cable as shown in Fig. 21. Make sure the motor cable is not able to get caught in any potential pinch points.



Fig. 21: Positioning the motor cable.

Step 4:

Replace the side guard as shown in Fig. 22a. Slide in the direction shown in Fig. 22b and re-secure the screws with a 1/8 Allen Wrench.



Fig. 22: Re-securing the side guard.

13 Replacing the 4x00 Y-Axis Motor Belt DOC #: 7301-0-US70-111318-AM-02-02





Step 5:

Replace the side cover and secure the three screws with a 1/8 Allen Wrench as shown in Fig. 23a-c.







Fig. 23: Re-securing the side guard.

Replacing the 4x00 Y-Axis Motor Belt 14



Proprietary & Confidential: This document contains proprietary information owned by Lincoln Electric Cutting Systems, Inc. and may not be duplicated, communicated to other parties, or used for any purpose without the express written permission of Lincoln Electric Cutting Systems, Inc. THIS DOCUMENT IS VALID FOR 24 HOURS AFTER PRINTING – Dated: 1/8/2019 support Cutting Systems, Inc.

Cutting

Systems

LINCOLN

ELECTRIC