

Symptoms:

Torchmate CAD will not display imported .dxf file created in Fusion 360.

Verification:

- After attempting to import the .dxf file created in Fusion 360, the CAD screen does not show the part created.
- The screen will “blink” and zoom into the material space.

Cause:

One of the existing Torchmate CAD files needs to be updated to translate the .dxf files produced from Fusion 360.

Solution:

1. Download the impdxf.zip folder from [here](#)
2. Extract the downloaded folder.
3. Copy the impdxf.dll file.
4. Paste the file onto the Torchmate CAD folder on the C: drive
5. Select the option to overwrite the existing file.